



JON M. HUNTSMAN, JR.
Governor

GARY R. HERBERT
Lieutenant Governor

State of Utah
DEPARTMENT OF NATURAL RESOURCES
Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report
Minerals Regulatory Program
July 19, 2007

Supervisor DRH

Mine Name: Timberline Rock Pit
Operator Name: Timberline Rock Pit, LLC

Permit number: S/049/053
Inspection Date: July 17, 2007
Time: 2:00 pm

Inspector(s): Dan Smith, Lynn Kunzler, DOGM
Other Participants: None
Mine Status: Inactive

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls,	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection:

Check status of site – Operator had phoned in thinking that the site had been reclaimed. Operator indicated that the property has now been sold to another party.

Inspection Summary:

There has been no apparent activity at this site since the April 4, 2007 inspection. The 5- acre SMO area has not been reclaimed. Several small pits (6-10 feet deep) were scattered across the area. The excavated material was generally located adjacent to each pit. These piles averaged 6-10 feet high.

Photos were taken to document site conditions.

Conclusions and Recommendations:

The operator needs to reclaim this site or transfer the permit to the new land owner. DOGM should continue to monitor this site when in the area.

Inspector's Signature *[Signature]*

LK:pb

O:\M049-Utah\S0490053-Timberline\inspections\Insp-07172007.doc



JON M. HUNTSMAN, JR.
Governor

GARY R. HERBERT
Lieutenant Governor

State of Utah
DEPARTMENT OF NATURAL RESOURCES
Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report
Minerals Regulatory Program
April 27, 2007

Supervisor RQZ

Mine Name: Timberline Rock Pit
Operator Name: Timberline Rock Pit, LLC
(Matt Carter)
Inspector(s): Lynn Kunzler, DOGM
Other Participants: None
Mine Status: No activity

Permit number: S/049/053
Inspection Date: April 4, 2007
Time: 8:30 am

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls,	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection:

This was a routine inspection while in the area.

Inspection Summary:

The site has not been active since last year. Most of the the 5- acre site is currently disturbed (several pits, overburden piles, etc.) During the inspection in May of 2006, a cessation order had been issued for operating outside the 5-acre limit for a small mining operation. The CO was terminated November 6, 2006 after being modified to allow reclamation of the area outside the proposed permit area. (The party responsible for operating outside the area had reclaimed and seeded the area subject of the CO prior to November 1 and has provided surety to assure successful revegetation.

Photos were taken to document site conditions.

Conclusions and Recommendations:

Continue to monitor reclamation success when in the area.

Inspector's Signature LK

LK:pb

O:\M049-Utah\S0490053-Timberline\inspections\Insp-04042007.doc